

**Flood Control Project Maintenance
Levee Inspections
2008 Channel Summary Report
Overall Unit and Item Ratings**

Tehama County Flood Control and Water Conservation District

McClure Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Salt Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	U

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Tehama County Flood Control and Water Conservation District

Channel
McClure Creek

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Channel Rating	A

**Flood Control Project Maintenance
Inspection Report - Channel 2008**

Tehama County Flood Control and Water Conservation District

Channel				Inspection Date	Inspector
McClure Creek				09/17/2008	Bob Duffey

Roll Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.009840 ° 122.200180 °	Y	1
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.009840 ° 122.200180 °	Y	2
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.007430 ° 122.171780 °	Y	3
4	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		40.007430 ° 122.171780 °	Y	4
5	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		10.017400 ° 122.146540 °	Y	5
6	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.017400 ° 122.146540 °	Y	6

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected
--	---

**Flood Control Project Maintenance
Inspection Report - Channel 2008**

Tehama County Flood Control and Water Conservation District

Channel	Inspection Date	Inspector
McClure Creek	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Upstream from extension of Truckee Avenue.	



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream from extension of Truckee Avenue.	



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Upstream from Highway 99 W bridge vegetation in the channel.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>	<p>C : Corrected</p>
---	---	---	----------------------

**Flood Control Project Maintenance
Inspection Report - Channel 2008**

Tehama County Flood Control and Water Conservation District

Channel	Inspection Date	Inspector
McClure Creek	09/17/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream from Hightway 99 W bridge dense vegetation in the channel.	



Report Line	5
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
upstream from Hamilton Road dense vegetation in the channel.	



Report Line	6
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream from Hamilton Road.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>	<p>C : Corrected</p>
---	---	---	----------------------

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Tehama County Flood Control and Water Conservation District

Channel
Salt Creek

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Channel Rating	A

**Flood Control Project Maintenance
Inspection Report - Channel 2008**

Tehama County Flood Control and Water Conservation District

Channel				Inspection Date	Inspector
Salt Creek				09/17/2008	Bob Duffey

Roll Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.157000 ° 122.164520 °	Y	1
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		40.153010 ° 122.159350 °	Y	3
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.151490 ° 122.157820 °	Y	4
4	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		40.147240 ° 122.155840 °	Y	5
5	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		40.147240 ° 122.154350 °	Y	6
6	Rivers, Channels & Designated Floodways	Erosion		U		40.156600 ° 121.163660 °	Y	2

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected
--	---

**Flood Control Project Maintenance
Inspection Report - Channel 2008**

Tehama County Flood Control and Water Conservation District

Channel	Inspection Date	Inspector
Salt Creek	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream of low water crossing vegetation in the channel.	



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Log and dense vegetation in the channel.	



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Logs and dense vegetation in the channel.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>	<p>C : Corrected</p>
---	---	---	----------------------

**Flood Control Project Maintenance
Inspection Report - Channel 2008**

Tehama County Flood Control and Water Conservation District

Channel	Inspection Date	Inspector
Salt Creek	09/17/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Logs and dense vegetation in the channel.	



Report Line	5
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream, approximately 100 feet from the confluence of the Sacramento River.	



Report Line	6
Location	
Category	Rivers, Channels & Designated Floodways
Item	Erosion
Downstream approximately 200 feet of erosion along the right bank.	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>	<p>C : Corrected</p>
---	---	---	----------------------