



2009 SAN JOAQUIN EROSION SURVEYS AERIAL ATLAS




Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch
April 2010





Index of San Joaquin Erosion Surveys Atlas






Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Mormon Slough



● 2009 Erosion Data




Plate 1



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Mormon Slough



● 2009 Erosion Data


Plate 2



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch


2009 Supplemental Erosion Survey

Mormon Slough



● 2009 Erosion Data


Plate 3



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Mormon Slough



● 2009 Erosion Data




Plate 4



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch


2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 5



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

French Camp Slough



● 2009 Erosion Data


Plate 6



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 7



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 8



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

San Joaquin River




● 2009 Erosion Data

Plate 9



Paradise Cut




● 2009 Erosion Data

Plate 11



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch


2009 Supplemental Erosion Survey



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Paradise Cut San Joaquin River



● 2009 Erosion Data




Plate 12



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 13



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Stanislaus River



● 2009 Erosion Data


Plate 14



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 15



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 16



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch


2009 Supplemental Erosion Survey

San Joaquin River



● 2009 Erosion Data


Plate 17



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Owens Creek Diversion



● 2009 Erosion Data


Plate 18



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

2009 Supplemental Erosion Survey

Ash Slough



● 2009 Erosion Data

Plate 19